

DEPARTMENT OF THE ARMY

WASHINGTON AQUEDUCT
U.S. ARMY CORPS OF ENGINEERS, BALTIMORE DISTRICT
5900 MACARTHUR BOULEVARD, N.W.
WASHINGTON, D.C. 20016-2514

January 17, 2017

Office of the General Manager

Mr. Andrew Seligman (3WP42)
NPDES Enforcement Branch
Water Protection Division
U.S. Environmental Protection Agency
1050 Arch Street
Philadelphia, PA 19103-2029

RE: INFORMATION REQUIREMENT, Section 308 of the Clean Water Act, 33 U.S.C. Section 1318 to Washington Aqueduct, 5900 MacArthur Boulevard, Washington, DC 20016, Baltimore District, US Army Corps of Engineers

Dear Mr. Seligman:

The following information is submitted in accordance with the subject request for information letter dated January 6, 2016. In our February 12, 2016, letter to you we said we would send monthly updates as of the 15th of the month reporting on dredging activity at the Georgetown sedimentation basins in the prior 30 days.

This update is for the period December 15, 2016, through January 16, 2017.

The commercial supplemental dredging operation was completed before the beginning of this reporting period. No material was removed from Georgetown basin 2 during this reporting period. This ends the commercial supplemental dredging. Because of ice formation during January and February, the Washington Aqueduct dredges for basins 1 and 2 at Georgetown have been removed from the water.

I certify that the information contained in or accompanying this submission to be true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations. I certify as having responsibility for the persons who, acting under my direct instruction, made the verification that is information is true, accurate, and complete.

Sincerely

Thomas P. Jacobus

General Manager

cc: Mr. James Bemis Proudly Providing Water to the Nation's Capital Since 1853